

COMTRONIC

C/ Mur 6 08760 Martorell ① 937 750 750 Fax 937 754 426 ④ info@comtro.com www.comtro.com



Table of contents

Prefix: CE-declaration	2
Preface	4
Safety references	5
Laser classes	6
Index: Standard protective control measures	6
General safety instructions	7
Mounting of the laser into the bracket	8
Mounting options for line lasers	
Fixing of the mounting	9
Line laser alignment in sawing and cutting applications	10
Line laser alignment in drilling applications	11
Cross laser alignment in positioning processes	
Mountings	13
Auxiliary mountings	15
Lasers and power supply	16
Operating the specific lasers	18
Trouble shooting and elimination of simple interferences	21
Brief description of ZM18	
Appendix	26
Power supplies	27
Index:IP classes, Index: Laser classes	29
Written guarantee	30
Letter of augrantee	32

2

4

Preface

Dear customer,

we wish you a lot of enjoyment and success with this device which was developed and constructed according to the latest standard of technology. In order to operate your device in a safe, professional and economical way, we kindly ask you to read our instruction manual carefully. If you follow our instructions you can avoid dangers, reduce the cost of repairs and downtimes, and raise the reliability and lifetime of our products. If you don't use the device according to the terms of the manual there may arise dangers for the operator or others or functional impairments of the device or other material. Therefore only use the device if it is in a sound condition and only according to all the terms of the manual. Our manual contains the guidelines that are important for a proper use of the device. Only sticking to these instructions is considered appropriate usage. For errors and risks, which arise due to an inappropriate usage, the manufacturer does not take responsibility.

Before you install or operate the device, please read the manual carefully.

Appropriate usage

The Z-LASER was developed to save time, to use material more effectively and therefore reduce costs. Here the light red laser beam serves as a visual display. For cutting and sawing the laser marks the cutting line, for drilling it marks the drill hole position with two crossing lines. For positioning in general points, crosses, lines or other patterns like hair crosses, concentric circles or multi-lines are also possible. Nowadays laser lines are also used as measuring lines in image processing or in car body measuring.

The **Ż-LASER** has an additional function in the field of safety at work. The red laser lines which indicate the cutting line or drill-hole warn the user to keep his hands off this section and can therefore avoid injuries.

Please use this "optical straightedge" for alignment and positioning only. Any other usage is not intended - consequences resulting from an inappropriate use are borne by the operator alone.

The device is only to be used by qualified, authorized and instructed personnel. The company has to instruct every person who uses the laser device or who is working near the laser about the dangers of laser beams and a responsible use of lasers. This kind of instruction is to be repeated at least once a year.

The operator has to make sure that the manual has been fully understood. The manual has to be kept with the laser device at all times.

Testing for transport damage

Before operating the laser for the first time please check the following points:

- 1. Check if the package (cardboard) is undamaged.
- 2. Check the laser for outside damages.
- 3. Potential damages of the package or defects on the delivered product have to be reported to the forwarding agent or to **Z-LASER** company within 24 hours.
- 4. Do only send back **Z-LASER**s in the original wrapping or with an adequate cushioning of foamed material.

Safety references

This manual has to be kept with the laser device at all times. The working area where the laser is installed has to be marked according to the legal requirements to avoid any damage to a third person. No mirrors may be brought into the beam path as this may create dangerous reflections.

In case of any malfunction turn off the device immediately!

General advice

Safety references serve the purpose of occupational safety and health and accident prevention. They have to be followed! Your cooperation is essential to prevent you and your colleagues from damage. Always work cautiously and be aware that most dangers are not "obvious". To guarantee a safe operating process the operator has to make sure that every person who works with or near the device has been informed about the possible dangers of laser radiation.

The responsibility for mounting and operating the device has to be determined and observed by the operator. You should refrain from any mode of operation which affects the safety of the device in a negative way. Any further national regulations are to be followed without restraint.

Alterations to the device are only allowed with a written permission from Z-LASER!

You can protect yourself against avoidable damages by consulting the current version of DIN EN 60825-1. Safety advice for the secure handling of laser products can also be found in DIN EN 60825 part 14 - "A users guide", especially chapter 4: laser radiation hazards.

The observation of these regulations is your responsibility!

In addition please note the national laser safety regulations valid in your country.

For instance in Germany such accident prevention regulations are published by the trade association "Berufsgenossenschaft" (BGV B2 and BGI 832). They must be observed.

Please check for the equivalent organizations and regulations for your country, for example in the US: OSHA and CDRH, in Canada: CCOHS, in Japan: JICOSH and JAISH, in the UK: HSE (Health and Saftety executive) and HSL (Health and Safety Laboratory), in France: INRS (Institut National de Recherche et de Securite), in Sweden: Swedish Work Environment Authority, in Poland: CIOP (Central Institut for Labour Protection), in the Netherlands: Arbeidsinspectie, in Luxembourg: ITM (Inspection du Travail et des Mines), in Austria: AUVA, in Switzerland: SUVA.

On a European level there is also the "European Agency for Safety and Health at Work".

5



Laser classes

Z-LASER manufactures its products according to international standards and declares the laser classes of its products following DIN EN 60825-1, IEC 825-1 and 21 CFR 1040.

The laser class is on the yellow or black/white/red (USA) warning label, which can be found on every laser. Never remove this warning label! It is absolutely necessary that the safety measures which result from each laser class are observed (see UVVs and norms).

Class	Standard protective control measures (according to DIN EN 60825)							
	These should be applied unless there has been a risk assessment legitimating other protective measures.							
1	No control measures are required for regular operation (this may not apply in case of maintenance or service).							
	For capsuled laser equipment containing a laser with higher output, the instructions on the warning signs delivered by the manufacturer are to be followed.							
	Special protective measures apply to local servicing of capsuled laser equipment.							
1M	No type of magnifying optical aids like binoculars, telescopes, microscopes, visual aids or magnifying glasses may be used for looking directly at the laser source, unless they have appropriate protection.*							
	Any external optics which might reduce beam divergence or diameter are to be avoided.							
2	Do not look directly into the beam.							
	Do not direct the beam towards others or to areas where others not involved in the laser operation might be present.							
2M	Do not look directly into the beam.							
	Do not direct the beam towards others or to areas where others not involved in the laser operation might be present.							
	It is to be ensured that the laser beam ends on a suitable, non-specular (i.e. not mirror-like) surface.							
	No type of magnifying optical aids like binoculars, telescopes, microscopes, visual aids or magnifying glasses may be used for looking directly at the laser source, unless they have appropriate protection.*							
3R	Avoid direct eye exposure to beam.							
	Do not direct the beam towards others or to areas where others not involved in the laser operation might be present.							
3B and 4	Class 3B and class 4 laser equpiment should not be used without previous risk assessment specifying the protective measures required for a safe operation.							
	Where it is possible within reason, constructive measures (like they are defined in IEC 60825-1) are to be used to downgrade the class of the laser to under 3B (this will usually mean to completely enclose the laser radiation to ensure a class 1 operation).							

^{*} The type of the potentially dangerous optical aid may be on the warning sign or included in the manufacturer's instruction manual.

General Safety Instructions

- The lasers are only designed for operating with the voltages given in the technical data. To avoid disturbances it is absolutely
 necessary to follow these instructions. Especially spikes and other disturbances of the electric network (for example caused by
 switching on heavy machines) may damage the laser. If it is not certain that these conditions can be fulfilled, the input
 voltage needs to be stabilized by appropriate measures (primary protection / voltage stabilizer, e.g. Z-LASER line filter
 ZNFI.
- High operating temperatures (> 45°C or > 113°F) reduce the lifetime significantly.
- Please do not operate the laser above the given IP classes:

First code number	Second code number			
Foreign objects protection	Water protection			
0: Unprotected	0: Unprotected			
1: Protection against large solid foreign objects > 50 mm	1: Protection against dripping water falling vertically			
2: Protection against medium-sized solid foreign objects > 12,5 mm	2: Protection against dripping water falling at an angle of 15°			
3: Protection against small solid foreign objects > 2,5 mm	3: Protection against spraying water			
4: Protection against grain-shaped solid foreign objects > 1 mm	4: Protection against splash water			
5: Protection against the ingress of dust	5: Protection against water jets			
6: Dust-proof	6: Protection against powerful water jets			
	7: Protection against temporary submersion			
	8: Protection against continuous submersion			

Example: IP64

6: Dustproof , 4: Shower water proof

Please remember: Oil and chemicals are not water! A water-jet proof laser is not necessarily protected against oil or chemicals!

IP values for our lasers: see page 29

7

8

Mounting of the laser into the bracket H0-40 / H0-20



Please unpack the laser and the mounting. If you have ordered a laser plus mounting, the mounting will be enclosed.



Move the laser carefully into the mounting. Pay attention to the stickers with the works number and the warning label. It is essential that they are not damaged.




Attention: when using the bracket H0: Please unscrew the chromed screw completely with a size 4 hex-wrench, then screw the clamping screw into the hole next to it with a size 2.5 hex-wrench, thereby spreading the mounting.




Tighten the size 4 socket screw again. For the bracket H0: Don't forget to remove the clamping screw before you tighten the socket screw.

Mounting options for line lasers



Rule of thumb for 45° -mounting: minimum mounting height $X \sim$ one third of the needed line length Z



Fixing of the mounting



For mounting H0 and every other mounting which can be put onto a shaft: Unfix socket screws, move the mounting to the required position on the shaft and tighten both socket screws.




For mounting H2 and every other mounting which can be screwed on using a slotted hole:
Put the mounting roughly into the required position and fix it with two screws through the platted hole legging some room.


with two screws through the slotted hole leaving some room to adjust the mounting. Then adjust the mounting to the exact position and tighten the screws.

o

10

Line laser alignment in sawing and cutting applications







The lasers should always be mounted perpendicularly above the saw blade (see Figure 1). You can also mount the laser laterally with the laser line is in continuation of the saw blade. However, if you put material onto the saw, the laser line will shift because of the difference in height due to the material and will not indicate the exact cutting course any more (see figure 2).

Hint: Make a cut as usual and leave the material there afterwards. Align the laser line exactly with the cutting edge. With the mountings H6 and H8 the laser can be adjusted very fast and exactly. Only a laser which is aligned 100 % correct will guarantee the desired success.

Line laser alignment in drilling applications






As described on page 10, the laser marking will shift due to the height of the material. To avoid this (and to ensure indicating the very spot where the drillbit actually hits the material), the two lasers need to be adjusted as follows: Each of the two laser lines has to illuminate the complete drill axis and not only one point, e.g. the drillbit.


Hint: Fix the drill in the drill chuck and align the two lasers one after the other in a way that the whole drill from the peak to the drill chuck will be illuminated centrically by the laser line (see figures above).

1

12

Cross laser alignment in positioning processes





The laser should always be fixed exactly perpendicular to the work space (see Figure 1). Optionally, it is of course possible to mount the laser with an inclination (see Figure 2), but in that case you have to be aware that the angles of the laser cross might change. If you are not able to choose a vertical position because of the mounting conditions, only tilt the laser parallel to any of the edges of the right-angled work space.

Hint: Place a right angle on the work space, where the laser cross is to be projected later. Then tilt the laser in a way that the intercept point of the laser lines meets exactly the vertex of the angle. Now rotate the laser in the mounting around its axis until the laser cross matches the 90°-angle on the work space.

Mountings

With all mountings you basically have the possibility to rotate the laser inside the mounting around its longitudinal axis.



НО

After loosening the lower hexagon socket screw the mounting H0 can be fixed to a 20 mm bar, then moved parallely and inclined. The upper part can be rotated by loosening the hexagon socket screw at the side.



With the mounting H2 you can move the laser laterally by loosening the screws in the slotted hole. The upper part of the mounting can be tilted after loosening the socket screw.



With the mounting H3 the laser can be moved laterally by loosening the screws in the slotted hole. The upper part of the mounting can be rotated in nearly every direction after loosening the socket screw on the ballshaped head joint.




The mounting HX is available in PVC. With its four screws the laser can be inclined, rotated and therefore precisely aligned in any direction.

13

H8

14



The precision mounting MXYZ is maintenance-free and free from backlash.


By tightening the hexagon socket screws the laser is fixed within the mounting.

By adjusting the screw (a) it can be rotated coaxially up to 360° .

By adjusting the screw (b) the laser can be rotated in angles of up to 20° seen from above.

By adjusting the screw (c) the laser can be parallelly moved up to 20mm.





With the mountings H6 and H8 a very easy and precise laser adjustment is possible.

By tightening the hexagon socket screw (a) the laser is fixed within the mounting.

By twisting the screw (b) it can be rotated around its own axis very exactly.

By adjusting one of the screws (c) or (d) the laser is rotated in angles seen from above.


By adjusting both of the hexagon socket screws together (c) and (d) the laser can be moved laterally to the left or right.



The mountings H2 and H3 can be fixed to the magnet mount BM. Due to the strong magnet on the bottom side, a lifting capacity of up to 2 kg is possible.



The mounting block BK can be put onto a 20mm bar. The mountings H2 and H3 can be fixed to the BK.



16

Lasers and Power Supply

Every laser has to be connected directly to the power supply system (ZPT-F, ZR, ZRX, ZRG-F) or to an enclosed mains adapter. Now it is ready to operate.

Connection plan for operating ZM18, Z-24, Z-24F with the power supply:





- 1: operating voltage +
 2: modulation + (Z-24, ZM18S/H only)
 3: operating voltage 4: modulation (Z-24, ZM18S/H only)

1. Wiring of the M12 plug for the laser:

- a) Unscrew the plastic housing of the M12 plug.
- b) Connect the positive and the negative cable according to the connector pin assignment! (see above)
- c) Screw the plastic housing back on the Lumberg plug and fix the cable by tightening the backside plastic cover.
- d) Put the Lumberg plug into the socket of the laser and tighten the threaded ring.

Note: The plug is to be tightened firmly but not with too much force. The use of any kind of tools for tightening the electric plug to the socket violently can lead to the damage of the laser and is considered as improper use which will lead to a loss of any warranty claim.



2. Connecting the cable to the NG-C-W power supply: DC Output

- a) The positive cable in socket +V
- b) The negative cable in socket -V
- c) DC OK (no connection)

ÁC Input


- a) the grounded conductor (PE) in socket
- b) the neutral conductor in socket N
- c) the phase in socket L

3. Connecting by cable



Position	Function	Colour
Pin 1	Voltage supply +	Brown
Pin 2	TTL Modulation	White
Pin 3	Voltage supply -	Blue
Pin 4	Analog modulation	Black





corrugated cable: operating voltage + round cable: operating voltage -



Please observe the ESD-protection measures according to IEC 61340-5-1 or ANSI/ESD S 20.20 when wiring the laser to your mains adaptor or when installing a plug. If you don't observe these rules some electronic components or the laser diode may be destroyed by electrostatic discharge. It is also possible that the laser diode is just damaged by that and will then break down completely some time after the damage.

17

18

Operating the single lasers

For the following lasers there are special possibilities:



The <u>ZA</u> is switched on and off by moving the ON/OFF switch back and forth. The switch can be removed for cleaning. Always attach the "OFF" in beam direction, otherwise the laser does not work. The ZA operates with a mignon battery.





ZM12



The **focus** of the laser $\underline{ZM18}$ (focusable version) is changed by turning the focusing ring. (see pp. 23-25 for more information on M18)

ZM12 lasers can be changed in focus with a key at the laser head.

* You can **focus** the laser to the thinnest possible and therefore best visible laser projection.



The **focus*** of the lasers $\underline{Z-24F}$, \underline{ZV} , \underline{ZFpeF} and $\underline{ZB-pe}$ is changed by turning the laser head.







The **focus*** of the lasers <u>ZPT-F</u> and <u>ZRG-F</u> can be adjusted by removing the protection cap and turning the inner screw with an allen key.

Please make sure to put the protection cap back on after focussing to avoid any intrusion of dust or water.










Lens covers provide extended periphery protection. Please only fasten them in the shown position, otherwise their function may be impaired.


19



With the ZT you can change the different optical heads by unscrewing the cap nut. Important: Only unscrew the nut when the laser is switched off, because without its head the laser becomes class 3R!









Trouble shooting and elimination of simple interferences

1. Error: No laser beam

Possible reasons for all lasers with mains supply:

- Is the device plugged in?

If so, is the control light on?

If not, please check whether there is mains voltage or whether the socket is defective.

- Can you rule out a broken cable?

Additionally for the model ZPT-F:

Is the external fuse defective? If so, please only replace it by a fuse of the same power. A signal (status) LED on the back of the device signals temperature problems by blinking:

* 1x blinking: There is a problem with the peltier device, which is responsible for the temperature exchange.

* 4x blinking: The inside temperature of the laser is below -30°C

- * 5x blinking: The inside temperature of the laser is above +55°C.
- * 6x blinking: The laser diode has a temperature above +70°C. * 7x blinking: The laser diode has a temperature below -30°C.

Possible causes for all lasers with wall power supply:

Is the adapter plugged in correctly?Is the connector plug of the laser correctly connected to the adapter?

- Can you rule out a broken cable?

- Is it possible that the power supply for the laser is instable or nonexistant? If you suspect that this may be the cause, you can check with the voltage at the exit of the mains adapter is as high as indicated. If not, please check if there is line voltage or if the socket is defective. If you have line voltage but you can't measure output voltage from the adapter, the mains adapter is defective.
- Is the adapter very hot? If so, maybe the overvoltage protection has responded to the temperature overload. In that case please do not try to fix the adapter yourself, but use another adapter.

Possible causes for lasers with battery operation:

- Battery/Accumulator existent and inserted correctly (polarity)?
- Battery/Accumulator discharged?

- Batterie case firmly screwed?

- On/Off-switch put on in the right direction? ("Off"-Position to front and the small magnet (inside grey) backwards!)

If you have made sure that the malfunction is not due to any of the causes mentioned above, then either the electronics or the laser diode are defective. In that case please send the laser back to us.

21

22

Error: Laser beam split

Phenomenon: laser line can be seen but is weaker than usual and has several lines.

Please don't mistake this phenomenon for an out of focus projection! (Tests for out of focus projection: see below)

If it is sure that the laser beam is split then the diode is damaged, i.e. a new laser is necessary.

Possible reasons:

The laser diode was damaged by an instable power supply (e.g. high voltage impulses) or a short-circuit. Before

replacing the laser you should check the cause!

The laser diode was damaged by electrostatic discharge (ESD). This can happen when touching the bare wires, when the cable plug is cut off or the laser was ordered with conductor sleeves only and the ESD warning label has been ignored. So for operations where you might touch wires, always make sure that you are sufficiently ESD-protected according to EC 61340-5-1 or ANSI / ESD S20.20.

3. Error: Out-of-focus projection

Is the optics window clean?

If not, clean the window carefully with cotton swabs and alcohol. Please do not use strong cleaning agents and avoid scratching by pressing too strong with the cotton swab!

Error: The laser switches off, but then on again after a short time (only ZPT-F models)

Possible reason: the ambient temperature of the laser is too high. The integrated cooling system switches off automatically at 40°. Protect it from potential other heat sources. Don't expose the laser to direct sunlight.

Brief description ZM18







Product emits laser radi-

1, 1M, 2, 2M, 3R, 3B

Avoid direct eye exposure to beam! (EN 60825-1: 2007)

- Warning label is enclosed and should be well visible. Please pay attention to the laser classes!
- By rotating the focus ring, the laser projection can be focused (from 100mm up to ∞).
- 3. M18 thread with two nuts for a simple installation in a mounting or a mounting angle.
- LED light = Laser on
 - No LED light = Laser off
 - LED blinking orange/green (only ZM18S and ZM18H) = internal temperature of 65°C is reached. At 85°C, the laser turns off, but the LED still blinks. – Look out for this!
- 5. M12 connector to provide fixed and secure connection to power supply, cable or customized solution (also see configuration scheme with ZM18S/H).
- 6. Fit e.g industrial plug to laser, screw softly by hand (without tool).

Troubleshooting:

- No laser light. Is plug and/or power supply connected, supply voltage available?
- No laser light. Damaged cabel/cable break or is power supply/power socket defective?
- No laser light. Are the pin connections correct?
- Diffuse projection: (if focusable) readjust focus ring
- Diffuse projection: If the optic appears "dirty" carefully, clean with a cotton bud and spirit.

If the troubleshoots above do not solve your problems, it is possible that there is a fault with the electronics or laser diode. If the laser diode is faulty, as per split or weak beam, please return the laser to our headquarters.



WPS-5-M12 (UK) Power supply



24

Installation into a mount with Ø 20mm, for exam-

Please do not fix the mount on to the front of the laser body as pressure can cause damage to the optics. Please fix the mount behind the focusing adjustment (where the silver label is located).




H2-20

Installation into a mount – for example with a H6-M18 (see image on the right) (alternative angle mounting)

1. Spin nut 1 on to the M18 laser thread

- 2. Screw the laser into the mount until you reach nut 1 (alternative: put into mounting angle)
- 3. Spin nut 2 from behind and fix both nuts softly with a M18 device.

able (VDA)





Configuration	n scneme ana moau	lation	cable (KB4)					
	ZM18B (Basic) + ZM18DM	2: / Pin 3: V 3: - 4: / Pin 2: T	Pin 1:Voltage supply + Pin 3: Voltage supply - Pin 2: TTL Modulation / [ZM18-DM: up to 100kHz Pin 4: Analog Modulation /; Continuos wave					
	ZM18S (Sta	ndard)	ZM18H (High-End)					
Pin 2: TTL 1: + 2: TTL	Voltage levels below ~2V are interpreted as logic 0 or "light off"; voltage levels above ~2V are interpreted as logic 1 or "light on". Please note that the switching threshold can vary slightly.							
3: - 4: Ana. Pin 4: Analog	, .	Applying a DC voltage between 0-1V at pin 4, the laser intensity is controlled. OV means the laser power is < 10% of the nominal power. 1V and above means the laser wi achieve 100% of the nominal laser power.						
Modulation	Analog intensity control (u digital TTL Trigger	,	APC: TTL up to 1 MHz; sinusoidal waves MHz; ACC: up to 20 MHz (diode depen					
General rule	Note that there is a linear characteristic between the two voltages! Both control inputs are tolerar to DC voltages up to 25V, therefore, by applying 24V to the laser, it can easily be switched on to 100% by bridging pins 1, 2 and 4. There is no need for an extra supply of 1V. You cannot destroy the laser in a 24 Volt system by wrong connections of input pins.							

Unfortunately, we sometimes receive return deliveries of lasers because the M12 connector is faulty or has broken pins. These defects cause unnecessary costs, which can be avoided! We would like to ask you to fix the delivered lumberg plug only by hand and NOT with any tools. About 2mm of the screw thread must be visible, do not fix it any further.

Z-LASER Optoelektronik GmbH does not assume liability for damages which were caused by faulty handling.



	ZM18B (Basic) + ZM18DM	ZM18S (Standard)	ZM18H (High-End)				
Mechanical specification	ons *						
Max. Dimensions	108mm x Ø 20mm (focusable version)	128mm x Ø 20mm (focusable version)	138mm x Ø 20mm (focusable version)				
Protection category		IP 67, dust-proof and waterproof					
Connection		M12 plug, 4-pin					
M18 industry housing	Chromed brass, with optic	head: anodised aluminium	Gold plated brass, with optic head: anodised aluminium				
Electrical specifications	*						
Supply voltage		5-30VDC +/- 5%					
Mode of operation	eration APC with current limiting (or CC) APC with current limiting		APC with current limiting or CC				
Modulation	ZM18B: Continuos wave ZM18DM: TTL Modulation up to100kHz	Analogue intensity control (up to 32 steps) and digital TTL trigger up to 1 kHz	APC: TTL up to 1 MHz; sinusoidal waves up to 5 MHz ACC: up to 20 MHz (diode depending)				
Protection	Reverse polarity and transient suppression / ESD	' '					
Optical specifications *							
Output	1	1-200mW (depending on wavelengt	h)				
Wavelength	635nm - 980nm	635nm - 980nm	405nm - 980nm				
Environmental condition	ons *						
Case temperature	-10°C up to +50°C (depend	-10°C up to +50°C (depending on wavelength; heat dissipation e.g. with mounting H8-M18)					
Storage temperature		-10°C up to +80°C					
Humidity		Max. 90%, non condensing					
MTTF at 25°C	> 30.000h (> 5.000h on green and blue wavelengths)						

^{*} Please have a look at the data sheets for further information, e.g. blue wavelengths or ZM18-green with 532nm. Do you need help? Please contact your country representative or visit www.z-laser.com.

25

26

Appendix

Line lengths at 45° mounting (-lg90)

Diode Power	visible line length at norm	al surrounding light (indoor)	optimal mounting height		
red (635nm)		green (532nm)	red (635nm)	green (532nm)	
3mW	1m		1m		
5mW	2 - 3m	4m	1,2m	2m	
10mW	3 - 5m	8m	2m	3m	
15mW	4 - 6m		2m		
20mW	7m	15m	3m	3m	
30mW	7 - 9m		3m		
40mW	11 - 15m	20m	3m	3m	
60mW		> 30m	3 - 5m	3-5m	
80mW	> 20m		5m		

Other available optics













Power supplies (wall-type)

WPS-5-M12 Power Supply (European & US/Japan plug) (alternative UK plug)

with 2m cable and M12 plug connector

V in = 100 to 240 VAC

V out = 5VDC I out = 1200mA

ΔVp-p: ca. 20mV



WPSB-3.5 Power Supply (European, US/Japan plug) (alternative UK plug)

with 29cm cable and Texas socket

V in = 100 to 240 VAC

V out = 3.5VDC I out = 1000mA

ΔVp-p: ca. 100mV



WPS-5 Power Supply (European, US/Japan plug) (alternative UK plug)

with 2m cable and Texas plug V in = 100 to 240VAC

V out = 5VDC | out = 1200mA

 ΔV p-p: ca. 20mV



Stylet Branch

VB4 Distributor box

for connecting up to 4 pcs. of laser ZB, ZD, ZF or ZT with a WPS power supply with ON/OFF switch and operation LED

2

28

Power supplies (for switch cabinet)

NG-CW-HD-3.5 "Heavy Duty" Power Supply for C-track in switch cabinet

Housing with 4 Texas sockets

V in = 85 to 275VAC

V out = 3.5 VDC I out = 1100 mA

ΔVp-p: ca. 50mV



NG-C-W-5M Power Supply for C-track in switch cabinet

V in = 100 to 240 VAC

V out = 5VDC I out = 3000mA

ΔVp-p: ca. 80mV



NG-C-W-24M Power Supply for C-track in switch cabinet

V in = 100 to 240 VAC

V out = 24VDC I out = 1000 mA

 ΔV p-p: ca. 150mV



^{*} Power supplies comply with the current EN norms

IP classes

Model	ZA	ZB	ZD	ZF	ZFpeF	ZM18	ZM12
IP	64	40	40	40	40	67	54
Model	ZPT-F	ZR	ZRX	ZRG-F	Z24/-F	ZT	
IP	65	65	65	65	64	40	

Laser classes according to EN 60825-1:2007

Output	1mW	3mW	5mW	10mW	15mW	20mW	30mW	40mW	50mW	60mW	80mW
Dot optics	Dot optics										
Elliptic dot	2	3R	3R	3B							
Circular dot	2	3R	3R	3B							
Line optics (exemplai	Line optics (exemplary)										
Standard line, gaussian distribution, 90° fan angle	1M	1M	1M	1M	2M	2M	2M	2M	3R	3R	3B

Line optics with different lenses (e.g. Powell) may have different laser classes, as well as changing the fan angle / focussing might lead to different laser classes.

29

30

Written guarantee

Z-LASER products are elaborately developed and well-engineered. A systematic quality management according to DIN EN ISO 9001 accompanies the complete production process. During the production of Z-LASER products, a multitude of parameters (e.g. laser power, beam quality etc.) are tested for deviations from the set value and are then documented.

Only products which lie within the determined set value range are released for sale. Every laser is tested again for correct functioning

You will only get certified quality from us. In spite of this diligence it is possible that a device breaks down during the guarantee pe-

Guarantee periods for each product family:

ZA family: guarantee for performance ZB, ZD, ZF-/ZFpeF, ZN, ZV, ZT, ZL, Z-24G product family: with Z-LASER-power supply unit 12 months, otherwise only zguarantee for performance (q.v. ESD-problem)

ZR, ZRX family: 12 months guarantee

ZPT-F family: 24 months guarantee (exeption: ZPT-F > 20 mW with 12 months guarantee) (internal counter for hours of operation)

ZRG-F family: 12 months guarantee, but with a maximum of 2 000 hours of operation (internal counter for hours of operation) **ZM18 family:** 24 months guarantee

ZM12 family: 24 months guarantee

Z-LASER warrants the product for the defined periods of time, from the date of delivery at Z-LASER. The warranty includes impeccable processing and functional efficiency. If deficiencies should appear in this regard, Z-LASER will replace or repair according to the following conditions:

- 1. The end user has to check the delivery immediately after the receipt and report possible damages in written form immediately, or at the latest within 2 weeks after delivery.
- 2. If damage already exists at the time of delivery and is noticed some time later (hidden damage), you must report this damage immediately and in written form.

3. The warranty is void,

- if the product is installed, stored or handled incorrectly,
- if the operating conditions with regard to supply voltage and environmental influences are not observed, if the product is operated outside the given specifications,

- if any changes to the device are made (e.g. opening, adjustment or modifications) without a written instruction by **Z-LASER** - if the label with the serial number has been removed, or

- if the damage can -completely or partially- be traced back to reasons that lie outside the device, or to the fact that the device has been connected to other objects that were not suitable.

4.	The guarantee includes	s only damages	that can be trac	ed back to material	l or production	faults and influ	uence the opera	tion of the
	device.							

- 5. The guarantee strictly excludes wear material.
 6. Z-LASER does not cover consequential costs, particularly not for the loss of production, dismantling, installation or reconnection.
 7. All the transport and insurance costs for returning the device to Z-LASER have to be paid by the customer in advance.

8. The warranty claim is only granted in connection with the completed and authorized letter of guarantee:

Any goods to be repaired or replaced shall be returned to *Z-LASER* at the customer's expense, if requested so by *Z-LASER*. If the goods are deemed to have a manufacturing defect within the warranty period, *Z-LASER* will repair or replace the goods at no charge and cover the cost of shipping them back to the customer. If it is found that the goods do not have a manufacturing defect, the customer must assume the charges for processing, dispatch and insurance, as well as the costs for the repair or the replacement of the device.

32

Letter of guarantee

COMTRONIC

C/ Mur 6 08760 Martorell 3 937 750 750 Fax 937 754 426 ₫ info@comtro.com www.comtro.com





Checked by

Please save this document!